
TO POWER SUPPLY CIRCUIT
MB-1 SBF-1 (B)
MB-2 M/B FUSE NO. 1 (B)
FB-44 F/B FUSE NO. 33 (IG)
FB-3 F/B FUSE NO. 8 (B)
WR
RY
GY
WL
BrR
33
FUSE (RELAY BLOCK)
7.5A
B225
32
Lg
B435
1
2
STOP LIGHT SWITCH
B65
MULTI JOINT CONNECTOR
B439
B438
3
BrW
B434
4
5
FUSE & RELAY BOX (F/B)
BrW
F9
F5
BrR
F: B159
A VDC(RD)-04
B VDC(RD)-04
23
24
28
30
MOTOR RELAY
C VDC(RD)-04
VALVE RELAY
B310
VDC CM
SOLENOID VALVE
FL INLET
FL OUTLET
FR INLET
FR OUTLET
RL INLET
RL OUTLET
RR INLET
RR OUTLET
PRIMARY CUT
PRIMARY SUCTION
SECONDARY CUT
SECONDARY SUCTION
D VDC(RD)-04
B65 (BLACK)
(PINK) B434
B438 (GRAY)
(BROWN) B435
B439 (GREEN)
F: B159 (BROWN)
B225 (BLACK)
B310 (BLACK)
RELAY BLOCK
WI-21619